

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Peter BOYCE BPB No. 0043	151	No 317-321 Mona Vale Road ST IVES	The certifier oversaw building works undertaken on the site that were not in accordance with the development consent including an additional concrete floor area of 72sqm being poured at first floor level The certifier issued a notice of an intention to issue an order that was inaccurate and would have been more appropriately issued under another section of the <i>Environmental Planning and Assessment Act</i>	Mr Boyce was reprimanded with report on practice	21 Dec 2007