

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Bernard COHEN BPB No. 0067	169	199 Parramatta Road FIVE DOCK	The certifier failed to respond to concerns raised by a complainant in a timely and efficient manner when it became readily apparent that the works being undertaken on the development site were causing damage to the complainants property	Mr Cohen was cautioned	23 May 2008