



Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Peter BOYCE BPB No. 0043	347	15 Inverallan Avenue, West Pymble	The certifier issued a construction certificate that was inconsistent with the development consent.	Mr Boyce was cautioned	02/07/2012