



Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Complaint No.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Peter Campbell BPB No. 0760	445	98/16	81 Blairs Road, Longbeach	Failed to ensure he was provided with installation certificates (fire separation and sound transmission) prior to issuing an occupation certificate.	Mr Campbell was Reprimanded & Fined \$1,500	11 May 2017