

## Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Mark <b>COGO</b>  BPB No. 0066	186	196-202 Mowbray Road and 61 Sydney Road WILLOUGHBY	The certifier allowed for construction commenced on site prior to council being advised of the appointment of a principal certifying authority The certifier failed to respond to correspondence prepared by council and an adjoining resident in a timely and efficient manner	Mr Cogo was reprimanded	31 Jul 2008