

## Board's Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Paul <b>ARAMINI</b>  BPB No. 0013	235	68-70 Courallie Ave HOMEBUSH WEST	The certifier issued an occupation certificate for a development notwithstanding that the building was not suitable for occupation or use as all hose reels installed in the car park were non compliant with the Australia Standard The fire safety certificate, being relied on by the certifier to issue the occupation certificate, did not state whether it is an interim or final occupation certificate, has no assessment date and has no legible name to the signature provided	Mr Aramini was reprimanded and fined a sum of \$1000	2 Jul 2009