

Summary of Disciplinary Action

Accredited certifier	Disciplinary action no.	Property address	Details of disciplinary matter	Disciplinary action	Date of decision
Paul Aramini BPB No. 013	277	16 Fitzroy Avenue Balmain	<ul style="list-style-type: none"> The plans accompanying the construction certificate issued by the accredited certifier are inconsistent with the approved development consent plans. The number of changes between the approved development consent plans and construction certificate plans has adverse impacts in terms of heritage and on general planning grounds. 	Mr Aramini was reprimanded.	22 April 2010